## **Commercial Roof Condition Inspection Form**

Applicant/Insured Name: L'Pa	avia Condo Assoc. Inc	Application/Policy#:	
Location Address Inspected:	4101-4204 L'Pavia Blvd, Venice, Fl 34292	Building Number Inspected:	Garage 1

Date of Inspection: 9/28/2023

This *Roof Condition Inspection Form* must be completed and signed by a Florida-licensed professional. The form will not be accepted without the dated signature of one of the following appropriately licensed inspectors:

- Licensed roofing contractor
- Licensed general contractor

Note: This form does not verify windstorm loss mitigation features.

ROOF (Clear photos showing the entire roof's surface and condition must be submitted with this form.)								
Primary Roof:								
Covering material:	Tile	If updated (check one	e):	<b>Overall Condition</b>	n of Roof:			
Roof age (years):	20 years			Excellent				
Remaining useful life:	10 years	Full replacement		Good	$\checkmark$			
Date of last update:	7/22/2003	Partial replacement		Fair (explain)				
Roofing Permit Verified:	✓ *Yes 🗌 No	% of replacement		Poor (explain)				
*Permit Application Date	: 2/11/2003							
Visible damage:								
(describe; e.g. curling/ lifted/ loose/		Any visible damage /deterioration?		Any visible signs of leaks?				
missing shingles or tiles, or punctures,		Primary roof		Primary roof				
blistering, drainage issues, or bare spots in gravel, or coating degradation, or cracking		🗌 Yes 🗹 No		🗌 Yes 🔽 M	No			
of asphalt, etc.)		Secondary Roof		Secondary Roof				
		🗌 Yes 🗌 No		Yes I	No			
Secondary Roof:								
Covering material:		If updated (check one):		Overall Condition of Roof:				
Roof age (years):				Excellent				
Remaining useful life:		Full replacement		Good				
Date of last update:		Partial replacement		Fair (explain)				
Roofing Permit Verified:	□*Yes □No	% of replacement		Poor (explain)				
*Permit Application Date	:	_						
Comments: (Additional Comments Required if Primary or Secondary Roof Condition is denoted as Fair or Poor):								
This Inspection Form and the information set forth in it are provided solely for the purpose of verifying that certain structural or physical characteristics exist at the Location Address listed above and for no other purpose. It is not intended to constitute legal or professional advice. The information provided should not be relied upon, or treated as, as substitute for specific advice relevant to particular circumstances. The undersigned does not make a health or safety certification or warranty, express or implied, of any kind, and nothing in this Form shall be construed to impose on the undersigned or on any entity to which the undersigned is affiliated any liability or obligation of any nature to the named insured or to any other person or entity.								
All Roof Condition Inspect			y a Florida-license	d roofing or genera	l contractor.			
I certify that the above statements are true and correct.								
Christopher J. Patek		941-483-1888						
Inspector Name (printed)		Telephone Number						
CSA		General Contractor	CG	C1510043	9/28/23			
Signature of Inspector		License Type	Lice	ense Number	Date			
"Any person who knowingly and with intent to injure, defraud, or deceive any insurer files a statement of claim or an application								

containing any false, incomplete, or misleading information is guilty of a felony of the third degree. F.S. 817.234"



















